

## Return of Empty Yarn Packaging (cops H8)

**1<sup>st</sup> step:**  
Fill the bottom of the box  
with empty bobbins  
H8 – 30 pcs



**2<sup>nd</sup> step:**  
Stick the second layer into  
the gaps  
H8 – 20 pcs



**3<sup>rd</sup> step:**  
Stick the third layer into  
the gaps but put the  
bobbins headfirst  
H8 – 24 pcs



**4<sup>th</sup> step:**  
Fill the gaps again with  
bobbins headfirst  
H8 – 25 pcs



**5<sup>th</sup> step:**  
**Second horizontal layer:**  
**1<sup>st</sup> layer bobbins**  
**horizontal**  
**H8 – 26 pcs**



**6<sup>th</sup> step:**  
**Second horizontal layer:**  
**2<sup>nd</sup> layer bobbins**  
**horizontal**  
**H8 – 26 pcs**



**7<sup>th</sup> step:**  
**Second horizontal layer:**  
**3<sup>rd</sup> layer bobbins**  
**horizontal**  
**H8 – 26 pcs**



**TOTAL H8**  
**177 bobbins / pallet**

---

(pallet is for transport in 2 layers  
pallet dimensions: 1200 x 1150 x 1100 mm)




**TOTAL separators H8**  
**21 pcs / pallet**

---

(pallet is for transport in 2 layers  
pallet dimensions: 1200 x 1150 x 1020 mm)



**TOTAL wooden pallets**  
**1200 x 1150 for H8**  
**22 pcs / pile**  
Dimensions: 1200 x 1300 x 2100 mm



**IMPORTANT!**

- put a wooden pallet under each box
- fill box only up to the edge
- close the box with the original lid
- pack smaller quantities of separators etc. in one box
- keep empty bobbins separate, sorted by type
- store all boxes dry